# MetaVue™

VS3200 Spectrophotometer



# **User Manual**





#### **CE Declaration**



Hereby, X-Rite, Incorporated, declares that this model is in compliance with the essential requirements and other relevant provisions of Directives 2014/30/EU (EMC), 2014/35/EU (LVD), and RoHS 2011/65/EU.

## **Federal Communications Commission Notice**

NOTE: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference in which case the user will be required to correct the interference at his own expense.

# **Industry Canada Compliance Statement**

This Class A digital apparatus complies with Canadian ICES-003.

Cet appareil numérique de la classe A est conforme à la norme NMB-003 du Canada.

# **Equipment Information**

Use of this equipment in a manner other than that specified by X-Rite, Incorporated may compromise design integrity and become unsafe.

WARNING: This instrument is not for use in explosive environments.



Instructions for disposal: Please dispose of Waste Electrical and Electronic Equipment (WEEE) at designated collection points for the recycling of such equipment.

#### **Proprietary Notice**

The information contained in this manual is copyrighted information proprietary to X-Rite, Incorporated.

Publication of this information does not imply any rights to reproduce or use it for purposes other than installing, operating, or maintaining this instrument described herein. No part of this manual may be reproduced, transcribed or translated into any language or computer language in any form or by any means: electronic, magnetic, mechanical, optical, manual, or otherwise; without the prior written permission of an authorized officer of X-Rite, Incorporated.

Patents: www.xrite.com/ip

"© 2019, X-Rite, Incorporated. All rights reserved"

X-Rite® is a registered trademark of X-Rite, Incorporated. All other logos, brand names, and product names mentioned are the properties of their respective holders.

## **Warranty Information**

X-Rite warrants this Product against defects in material and workmanship for a period of twelve (12) months from the date of shipment from X-Rite's facility, unless mandatory law provides for longer periods. During such time, X-Rite will either replace or repair at its discretion defective parts free of charge.

X-Rite's warranties herein do not cover failure of warranted goods resulting from: (i) damage after shipment, accident, abuse, misuse, neglect, alteration or any other use not in accordance with X-Rite's recommendations, accompanying documentation, published specifications, and standard industry practice; (ii) using the device in an operating environment outside the recommended specifications or failure to follow the maintenance procedures in X-Rite's accompanying documentation or published specifications; (iii) repair or service by anyone other than X-Rite or its authorized representatives; (iv) the failure of the warranted goods caused by use of any parts or consumables not manufactured, distributed, or approved by X-Rite; (v) any attachments or modifications to the warranted goods that are not manufactured, distributed or approved by X-Rite. Consumable parts and Product cleaning are also not covered by the warranty.

X-Rite's sole and exclusive obligation for breach of the above warranties shall be the repair or replacement of any part, without charge, which within the warranty period is proven to X-Rite's reasonable satisfaction to have been defective. Repairs or replacement by X-Rite shall not revive an otherwise expired warranty, nor shall the same extend the duration of a warranty.

Customer shall be responsible for packaging and shipping the defective product to the service center designated by X-Rite. X-Rite shall pay for the return of the product to Customer if the shipment is to a location within the region in which the X-Rite service center is located. Customer shall be responsible for paying all shipping charges, duties, taxes, and any other charges for products returned to any other locations. Proof of purchase in the form of a bill of sale or receipted invoice which is evidence that the unit is within the Warranty period must be presented to obtain warranty service. Do not try to dismantle the Product. Unauthorized dismantling of the equipment will void all warranty claims. Contact the X-Rite Support or the nearest X-Rite Service Center, if you believe that the unit does not work anymore or does not work correctly.

THESE WARRANTIES ARE GIVEN SOLELY TO BUYER AND ARE IN LIEU OF ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING BUT NOT LIMITED TO THE IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR APPLICATION, AND NON-INFRINGEMENT. NO EMPLOYEE OR AGENT OF X-RITE, OTHER THAN AN OFFICER OF X-RITE, IS AUTHORIZED TO MAKE ANY WARRANTY IN ADDITION TO THE FOREGOING.

IN NO EVENT WILL X-RITE BE LIABLE FOR ANY OF BUYER'S MANUFACTURING COSTS, OVERHEAD, LOST PROFITS, GOODWILL, OTHER EXPENSES OR ANY INDIRECT, SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES BASED UPON BREACH OF ANY WARRANTY, BREACH OF CONTRACT, NEGLIGENCE, STRICT TORT, OR ANY OTHER LEGAL THEORY. IN ANY EVENT OF LIABILITY, X-RITE'S MAXIMUM LIABILITY HEREUNDER WILL NOT EXCEED THE PRICE OF THE GOODS OR SERVICES FURNISHED BY X-RITE GIVING RISE TO THE CLAIM.

# **Table of Contents**

1.	Introduction and Setup	4
	How to Use this Manual	4
	Packaging Contents	4
	Connecting the Power Supply	5
	Connecting the USB Cable	6
	Cable Channel	6
	Operation Button	7
	Status Indicator	7
	Instrument Slider Positions	7
2.	Measuring Samples	8
	Important Sample Information	8
	Measurement Procedure	8
3.	Cleaning the Instrument	10
	General Cleaning	10
	Cleaning the Instrument Lenses (weekly or whenever visible contamination is present)	10
	Cleaning the White Calibration Reference (weekly or whenever visible	
	contamination is present)	11
4.	Calibrating	13
5.	Appendices	14
	Service Information	14
	Troubleshooting Tips	15
	Technical Specifications	16
	Green Tile Color Check	17

# 1. Introduction and Setup

The VS3200 instrument is used to evaluate and identify colors in industrial applications. The instrument reads color samples from a variety of materials including paper, plastic, textiles, and various painted objects. The instrument can be adjusted from 2 mm to 12 mm target size on a sample.

The VS3200 requires an AC adapter and USB communication to the host computer. Connections are located at the back of the instrument.



#### How to Use this Manual

This manual is intended to provide setup, operation, and general maintenance of the instrument. Specific software application information is available in the software help system.

## **Packaging Contents**

Your instrument packaging should contain all the items listed below. If any of these items are missing or damaged, contact X-Rite or your authorized representative.

- VS3200 instrument with integrated calibration reference
- Green tile and holder
- USB interface cableBacker mat
- Cleaning Kit
- Power supply (X-Rite P/N SE30-210) and line cord
- Documentation and registration material


Calibration certificate

#### **Optional Accessories**

- VS3-802 Instrument Stand
- VS3-800 Adjustable Stand
- VS3-810 Benchtop Stand

# **Connecting the Power Supply**

- Verify the voltage indicated on the power supply complies with the AC line voltage in your area.
- 2. Feed the small plug from the power supply through the cable opening on the side of the instrument.
- **3.** Insert the plug into the input connector at the back of the instrument.



**4.** Plug the detachable line cord into the power supply and plug the line cord into the wall receptacle.




Operational hazard exists if a power supply other than X-Rite SE30-210 is used.

## Connecting the USB Cable

**IMPORTANT:** You must install the USB driver before connecting the instrument to your computer.

- Install the software application if not already installed. Refer to the software documentation for additional information.
- 2. Feed the square end of the USB cable through the left side or right side cable opening of the instrument.
- 3. Plug the square end of the USB cable into the connector at the back of the instrument.
- **4.** Plug the USB cable into an available port on your computer.



## **Cable Channel**

The cable channel located on the back of the instrument is used to secure the power supply and USB cables in place. The cable channel helps prevent the cables from inadvertently disconnecting, or interfering with sample measurements or cleaning when the instrument is resting on its back. The cable channel is used when the cable are routed out the right side of the instrument.



### **Operation Button**

The operation button is used to initiate a measurement after the sample is placed under the slider.

#### Status Indicator

The status indicator conveys a variety of instrument conditions, such as calibration and measurement status. Refer below for additional indicator conditions.

- Off: Instrument is off (not plugged in).
- Solid Blue: Booting up before firmware starts.
- Pulsing Blue: Instrument is in standby mode.
- Solid Green: Calibrated and ready to measure.
- Blinking Green: Measurement or calibration in progress.
- Solid Red: Firmware startup completed, ready for connection, or not calibrated.
- Blinking Red: Hardware error mode, cannot measure or calibrate.



#### Instrument Slider Positions

The instrument slider has three positions to perform various functions. Below are images of the slider position from the front and bottom of the instrument.

#### **Measurement and Side Sensor Calibration Position**





White Calibration Position





**Cleaning Position** 





# 2. Measuring Samples

The instrument measures samples under the slider at the bottom. It can take color measurements from almost any clean, dry surface that is reasonably flat. The sample should rest flat and steady below the slider. The sample can be viewed on a preview window within the application for easy positioning.

## **Important Sample Information**

- The sample area to measure must be at least 2 mm to 12 mm in diameter.
- The sample should be opaque (solid), not clear or translucent.
- Consistency in positioning should be maintained from standard to sample to achieve best results.
- The measurement region of interest should be centered in the measurement opening.
- Oddly shaped samples may require a fixture to allow proper positioning below the slider.
- For thin samples, ensure that the sample is placed on the supplied sample backer mat before measuring. The backer mat provides the proper background color to ensure measurement accuracy.
   To use, position the instrument directly over the backer mat.




 For best color measurement results, position the sample surface so that it is parallel (or flat) with respect to the instrument's four feet.

#### **Measurement Procedure**

- 1. Start the color match function in the application.
- 2. Make sure the slider is in the measurement position.

3. Place the sample under the slider until the area to measure is positioned within preview window in the application. If the sample being measured fills the complete preview window skip to Step 5, no targeting adjustments are required. If the sample does not completely fill the preview window, continue to Step 4 for information on adjusting the targeting size to fit the sample.

**NOTE:** If the sample is large or oddly shaped, position the instrument on its back and locate the sample against the slider. Use the preview window in the application to guide the sample to the desired measurement location. Refer to the next page for positioning illustration.



- 4. In the application, select the measurement area from Large (12 mm) to Small (2 mm) using the Target Size slider. The default setting is 12 mm.
- 5. Initiate the measurement by pressing the Operation button on the instrument or from the software application.

The status indicator changes from solid green to blinking green during the measurement.

# **Large Sample Positioning Technique**



# 3. Cleaning the Instrument

Your instrument requires very little maintenance to achieve years of reliable operation. However, to protect your investment and maintain measurement accuracy, a few simple cleaning procedures should be performed once a week.

# **General Cleaning**

The exterior of the instrument may be wiped clean with a cloth dampened in water or mild cleaner.



**NOTE:** DO NOT use any solvents to the clean the instrument, this will cause damage to the cover.

# Cleaning the Instrument Lenses (weekly or whenever visible contamination is present)

Important: The instrument must be calibrated after cleaning the lenses to ensure sample measurement accuracy. Refer to Section 4 after cleaning.




**NOTE:** Use of an abrasive material or unnecessary rubbing may scratch the lens surface and eventually cause permanent damage.

- 1. Place the instrument on its back.
- 2. Position the instrument slider to the back to gain access to the lenses.



3. Using one of the supplied lens cleaning tissues, clean all four lenses by wiping in a circular motion.



**4.** Place the instrument back upright and clean the calibration references. Refer to Cleaning the White Calibration Reference that follows.

# Cleaning the White Calibration Reference (weekly or whenever visible contamination is present)

Caution should be used when cleaning the calibration references. Color measurement accuracy is directly dependent on maintaining clean, contamination-free calibration references. Be careful not to touch the reference surfaces during normal calibration and measurement. Both white references are critical to calibration and measurement.

- 1. Position the instrument slider to the white calibration position.
- Use clean, low-pressure air to remove any dust or debris from the white reference. If a more thorough cleaning is required, clean with one of the supplied wipes.



- 3. Position the instrument slider to the measurement position.
- **4.** Use clean, low-pressure air to remove any dust or debris from the measurement reference. If a more thorough cleaning is required, clean with one of the supplied wipes.





**Caution:** If the calibration or measurement reference is cleaned with the supplied wipes, wait until the reference is completely dry before performing a calibration or measurement.


5. Perform a white calibration. Refer Section 4 for procedure

# 4. Calibrating


The VS3200 should be calibrated at least once a day. The calibration reference is mounted on the instrument slider. Refer below for calibration procedure.

After a calibration is initiated:

 If not already done, position the instrument slider so that the white calibration reference is located below the lenses.



- Select the appropriate option in the software application to initiate the white calibration measurement.
- After the white calibration measurement, the status indicator changes from blinking green to solid red. Position the instrument slider to the measurement position.



- Select the appropriate option in the software application to initiate the side sensor calibration measurement.
- After the target window calibration is completed, the status indicator changes from blinking green to solid green. This is an indication that the calibration procedure was successful.

# 5. Appendices

#### Service Information

X-Rite provides repair service to their customers. Because of the complexity of the circuitry, all warranty and non warranty repairs should be referred to an authorized service center. For non warranty repairs, the customer shall pay shipping and repair cost to the authorized service center, and the instrument shall be submitted in the original carton, as a complete unaltered unit, along with all the supplied accessories.

X-Rite, Incorporated has offices around the world. You can contact us using one of the following methods:

- To identify the X-Rite service center nearest you, please visit our web site (www.xrite.com) and click the Contact Us link.
- For online help, visit our web site (<u>www.xrite.com</u>) and click the **Support**link. Here you can search for software or firmware updates, white papers,
  or frequently asked questions which can quickly resolve common user
  problems.
- Send an e-mail to Technical Support (<u>casupport@xrite.com</u>) detailing your problem and listing your contact information. Use "VS3200" as the subject in your email.
- For sales questions or to order cables and accessories, visit our web site (www.xrite.com) or contact your nearest X-Rite dealer or service center.
- Problems and questions can also be sent to your local
   X-Rite office listed on our web site. You may also contact
   X-Rite using one of the numbers listed on the back page of this manual.

# **Troubleshooting Tips**

Prior to contacting X-Rite support department for instrument problems, try the applicable solution(s) described below. If the condition persists, contact us using one of the methods listed in the Service Information section.

#### Instrument not responding:

 Ensure power supply is connected to the instrument and the AC wall receptacle.

# Measurement error or results appear inaccurate:

- Lenses are dirty and require cleaning. Refer to Cleaning the Instrument Lenses in Section 3.
- Problem with the sample or sample positioning. Refer to Important Sample Information in Section 2.

#### Repeated calibration failures:

 Clean the white calibration reference. Refer to Cleaning the Calibration Reference in Section 3.

### Repeated sample measurement failures:

- Lenses are dirty and require cleaning. Refer to Cleaning the Instrument Lenses in Section 3.
- Ensure the sample is being positioned correctly. Refer to Important Sample Information in Section 2.
- Calibrate the instrument.
- Close and restart the software application.

## Instrument and software not communicating:

- Check the USB cable connection.
- Close and restart the software application. If this does not solve the problem, reboot the computer.
- Remove power from the instrument, reapply power and see if the condition is corrected.


# **Technical Specifications**

General	Performance
Instrument Type: Spectrophotometer	Warm up Time: 60 seconds
Geometry: 45°/0°	Measurement Time: < 8 seconds
Monochromator: Spinning filter wheel	Cycle Time: 1 sec. time interval between
	measurements
Light Source: Full spectrum LED	Ambient Light Rejection: 1000 Lux
Measurement Size: Variable virtual pickup	White Repeatability: 0.025 DEab
spot size (2 mm – 12 mm)	
Image Sensor: CMOS camera chip	Inter-Instrument Agreement: 0.15 DEab
	average
Measuring Distance: 1.96 in. (50 mm)	Calibration Interval: >= 24 hours
Insensitivity to Depth of Measuring Field:	Measurement Area: 2 to 12 mm
±0.09 in. (2.5 mm)	
<b>Operating Temp</b> : 10° - 40°C (50° – 104°F)	Spectral Range: 400 nm to 700 nm
Ambient	
Operational Humidity: 0 - 85%	Spectral Interval: 10 nm
non-condensing	
<b>Storage Temp</b> : -40° - 70°C (-40° – 158°F)	Product Life: 7 years (target)
Operating Voltage: 24 VDC @ 2.0 A	LED Life: 15,000 meas/year
Communication I/O: USB 2.0 (Type-B	
Interface connector)	
Overall Size: L: 9.75 in. (24.76 cm), W: 7.1 in.	
(18.03 cm), H: 7.25 in. (18.41 cm)	
<b>Weight:</b> 5.55 lbs. (2.51 kg)	
Safety Compliance	
UL 61010-1,	
Usage: Indoor Only	
Altitude: 2000 m	
Pollution Degree: 2	
Overvoltage: Category II	


Design and specifications subject to change without notice.

#### **Green Tile Color Check**

- Perform a calibration procedure if you have not already done so. Refer to Section 4 Calibrating.
- 2. Make sure the slider is in the measurement position.
- Position the instrument on its back and attach the tile holder to the slider by first inserting the pin at the bottom into the hole in the slider and rotating upward. The magnets on the underside will secure the tile holder to the slider.




**NOTE:** The top edge of the tile holder must extend over the end of the slider to ensure that it is properly seated.





- **4.** Remove the protective cap from the green tile.
- 5. Make sure the green tile is facing the slider and position the tile with the "notch down" over the tile holder. Lower into the tile holder slot until the notch aligns with the tab at the bottom.





Properly positioned green tile

- **6.** Initiate the green tile check procedure from the software application.
- After measurement, remove the green tile from the tile holder and reinstall the protective cap.
- 8. Store the green tile and tile holder in a dry, dust free area, away from direct exposure to light.



Corporate Headquarters X-Rite, Incorporated 4300 44th Street SE Grand Rapids, Michigan 49512 Phone 1 800 248 9748 or 1 616 803 2100 Fax 1 800 292 4437 or 1 616 803 2705

European Headquarters X-Rite Europe GmbH Althardstrasse 70 8105 Regensdorf Switzerland Phone (+41) 44 842 24 00 Fax (+41) 44 842 22 22

Asia Pacific Headquarters X-Rite Asia Pacific Limited Suite 2801, 28th Floor, AXA Tower Landmark East, 100 How Ming Street Kwun Tong, Kowloon, Hong Kong Phone (852)2568-6283 Fax (852)2885 8610

Please visit www.xrite.com for a local office near you.