eXact Basic Plus
Densitometer

Best-in-Class for Measuring All Aspects of CMYK in the Pressroom

By leveraging the eXact Basic Plus print and packaging operations can rest assured that color accuracy and consistency will be applied through the entire print process. In addition to measuring CMYK, Density, and Tone Value, this densitometer is designed specifically to allow operators to compare to standards with Pass/Fail indication and provides additional functions, such as Trapping, Contrast, Trend View and Print Curve View. As part of the comprehensive eXact family of products, the eXact Basic Plus is the ideal choice for those who print CMYK in the pressroom and verify all aspects for density.

The eXact Basic Plus is also available in a Xp model, that is specifically designed to solve the unique challenges of measuring flexible films.

Benefits

- **Accurate and Consistent**
  Integrated white calibration ensures the highest accuracy and consistency.
- **Best-in-Class to Support All Aspects for CMYK Densitometry**
  Allows job oriented working with pass/fail indication for all color patches of the color bar, to ensure color accuracy and consistency through the entire print process.
- **Configurable**
  Allows the user to easily configure the instrument as well as the flexibility to control all elements on a selected job.
- **Efficiency**
  eXact is built to bring efficiency to your operation with its ability to automatically detect the color and patch type, providing the measurement result in the view configured by the user.
- **Expandable**
  The eXact Basic Plus and eXact Xp Basic Plus model can be upgraded any time by password to the eXact Standard or eXact Advanced models.

For more information regarding this product, visit **www.xrite.com/exact-basic-plus**

Features and Specifications for eXact Basic Plus

Measurement Functions

	Basic Plus
Colors	
CMYK	X
Densitometry	
Density	X
Density Trend	X
All Densities, CMY Balance	X
Tone Value	X**
Tone Value Increase	X**
Print Characteristics	X**
Trapping	X
Contrast	X
Hue Error & Grayness	X
Special	
Printing Plate	X

Measurement Features

	Basic Plus
Security	
Setting Password protection	X
Others	
Pass/Fail Indication	X
Averaging	X

Measurement Parameters

	Basic Plus
Measurement Conditions	
M0, M1, M2, M3***	X
Density Status	
ISO Status A, ISO Status E, ISO Status I, ISO Status T, Status G	X
Density White Base	
Absolute, Paper	X

Data Interface

USB	X
Bluetooth	O*

Software

eXact Manager	X
DataCatcher	X

X: Included   O: Optional   * Bluetooth is available for most countries.
Work with your sales representative to identify if it is available option in your region.
** Including SCTV   *** M3 option not available for Xp models

eXact Basic Plus with USB cable, Power Supply, CD with software and documentation, Docking/Charging Station, Quick Start Guide, and Carrying Case.

Service Support & Warranty

Drawing on our extensive color expertise, X-Rite offers the right level of services on-site, online or on the phone with industry-leading response times, to support and nurture your business. With global full-service contracts, you can ensure your devices are well maintained through X-Rite's Annual Five Point Checkup, uniquely developed to keep devices performing to original specifications. For more information about extended support options, visit www.xrite.com/extended-warranties-services.

FIND YOUR EXACT

xrite.com/exact-basic-plus