



Before you can begin using NetProfiler, you will need a NetProfiler account. If you already know your User ID, password, and organizational alias, please proceed. If you do not have this information, you will need to obtain this information from your companies NetProfiler Administrator. If you are the administrator and need to set-up your accounts, please see page 8 for information.

Installing and Using the Software

Your new software is contained on the USB Flash Drive that you will find in the box with your tile set.

 Insert the Flash Drive into an Open USB port on your computer, if this is the first time you have connected the flash drive to your computer, you will see a popup message in the lower right hand corner of your display stating "Found New Hardware". It will take a few moments for your computer to find the correct driver and associate it with this drive. Once done you will see another popup message stating that "Your new hardware is installed and ready to use".



Windows XP

On a Windows XP system you will see windows similar to those that follow <u>Skip to the next page for Windows 7 systems</u>

 You should then see the following window appear, DO NOT CLICK "OK", "Enter" OR "Cancel" JUST YET.



• Scroll down and double click on "Open folder to view files using Windows Explorer"



• Double click the file titled START_HERE to begin

🤝 BOB (E:)		_ 🗆 ×
File Edit View Favorite	es Tools Help	
🕒 Back 🔹 🕥 🗸 🏂	🔎 Search 📂 Folders 🛄 🕶	
Address 🖙 E:\		🖌 🔁 Go
	Application	
File and Folder Tasks	START_HERE.hta	
	🔤 sum.fva	
Other Places	*	
👮 My Computer	•	

If you have completed the above steps on an XP system you may move ahead past the Windows 7 instructions to the "Dashboard" screen (Page 4)

NetProfiler 3 Getting Started Guide - © 2011 X-Rite, Incorporated. All Rights Reserved.



Windows 7

On a Windows 7 system you will see windows similar to those that follow

• You will see the following window, if there is no option to "Open window to View Files" like here, click the Red X to close this window.



- Click the Start button in the lower left hand corner of your screen, and then click on the word computer
- You will see a window as shown below, single click on the "Kingston" thumb drive in the left hand column, then double click on the file named START_HERE in the right hand column





You will see the following "Dashboard" screen

	Welcome to NetProfiler 3	x ∙rite
Step 1:	View the Getting Started Guide A printed copy of this was included in the package you received	-
Step 2:	Watch the Training Video Full Screen	
	Ready	
Step 3:	Install the Software on your PC Note: You MUST install the software on your PC even if you plan on running it from the Elash Drive	
		V

- 1. "<u>View the Getting Started Guide</u>" As noted above, a printed copy of this was included in the package you received. A digital copy is included here for your convenience.
- 2. "Watch the Training Video" This would be recommended for everyone using this version of NetProfiler for the 1st time. Even if you have used NetProfiler in the past, the interface has been updated. To begin the video you may click on the right pointing triangle in the lower left hand corner of the player, or on the words "Full Screen". To exit full screen mode, press the Escape "Esc" key on your computer keyboard. The video will prompt you to pause and minimize the video at specific points so that you may complete that step in the software.
- "Install the Software on your PC" During installation choose the option to "Install and run from Local Hard Drive" unless you need to use NetProfiler from a computer which does not have internet access. If this is the case please read the instructions on page 5.

NetProfiler 3 Getting Started Guide - © 2011 X-Rite, Incorporated. All Rights Reserved.

Running from a computer which does not have internet access

X·rite

During installation, you will be prompted to either "Run from USB Drive" or "Install and run from Local Hard Drive". The suggested method is to install and run from your local hard drive. The option to run from the USB Drive has been added to NetProfiler 3 for those customers who find it necessary to generate profiles from a computer that does not have access to the internet. If this is your situation, choose the option to "Run from USB Drive" on those machines which do not have internet access.

Please note that when running in this mode you must build your first profile on a computer which does have internet access, and has the software installed to be run from the local hard drive. This downloads the calibration data for your tile set, and your license information to the flash drive. After this initial profile you may create additional profiles using computers which do not have internet access.

After building profiles from your computers with no internet access, you may upload your profile information to the server by connecting the flash drive to a computer which has access and launching the NetProfiler application. The information will automatically synch. After a minute you may close the application and remove the flash drive.

🕞 Setup - Net Profiler3		_ 🗆 🗵
Select Additional Tasks Which additional tasks should be performe	d?	×
Select the additional tasks you would like 9 then click Next.	ietup to perform while installing Ne	etProfiler3,
Run from USB Drive		
${f C}$ Install and run from Local Hard Drive		
	< Back Next >	Cancel

IMPORTANT NOTES:

- Once you have started the software, if you want to Profile your instrument, please click on the "*Profile*" button, not the "*Activate*" button.
- If you are using a hand-held instrument your kit will include a "NetProfiler Base Assembly". This is used to hold the NetProfiler tiles as you measure them. Position the tiles into opening, aligning notch on the tile to the tab on the base. The shoe of your instrument will fit into this assemble just as it does with your calibration reference.
- If you are using a hand-held instrument, you will have an option to select "*Closed Shoe*" mode. Only select this option if you are using the instrument in a fixture where you need to activate readings from the software.

Control Center NetProfiler3 Languages	Beta Version (expires 11/16/2011)	_ ×
	Work Space Help	
Administration	NetProfiler3	Documentation
Activation/Registration	•.	Quick Start Guide
NetProfiler Website	SN: CI52000160 Copyright © 2011 X-Rite, Incorporated. All Rights Reserved. Version: 3.00 (B01)	Library
	Instrument Type CI52 ClosedShoeMode	Support
Related & Online Store	Profile Valida	Support
Related Products	Closed Shoe Mode	



• You will need to enter your tile set number into the NetProfiler software. This number is contained on a sticker on your tile set. This number will have a format similar to HHS###C, or BTS###C.



- After calibrating your instrument the 1st time you will be performing a repeatability test on the white and dark blue tiles from your NetProfiler tile set. If using a handheld instrument in "open shoe" mode, you will need to press and hold your instrument in the read position until a series of measurements is completed

 you will see a progress bar in the software as these readings are taken.
- After the repeatability section, you will be asked to once again calibrate your instrument, be sure to go back to the calibration reference that came with your instrument.
- After this second calibration, you will be prompted to read each one of the tiles in your NetProfiler tile set. Each tile will be read just once; there is no reason to hold the instrument in the read position for an extended period during this portion of the profiling process.
- After completing the profiling process, you will want to click "Store New Profile" to save this profile.

NetProfiler Administrator Information

Setting Up Your NetProfiler Account and Registering Your Instrument

Getting started

Before you can begin using NetProfiler to maintain the accuracy and consistency of your measurement devices, your organization will need a NetProfiler account, a NetProfiler Administrator, and your spectrophotometers registered.

NetProfiler Administrator

As the administrator you will have full access to all functions and information concerning your NetProfiler account and will have the ability to create users and set access levels for your account. If your organization has more than one location, you may create sub-organizations. To create your account, please complete the form on the last page of this document and fax or email it to us (using the contact information on the form). We will setup your NetProfiler account and provide login information. You can then setup your individual user accounts.

PANTONE[®] NetProfiler 3 Getting Started Guide

Logging in

When you receive your login credentials, you will be able to log in to your account at the following location:

http://netprofiler.xrite.com/

The NetProfiler Web Based Functions Online Help System contains instructions for creating new users. If you require additional assistance, please email casupport@xrite.com or call us at 1-888-826-3042, option #2.

NetProfiler Client Software

Your NetProfiler Organizational Alias, User ID and password will also be required to login to the NetProfiler 3 client software.



NetProfiler is a subscription based service and your subscription is associated to the serial number of your spectrophotometer. Your instrument will have to be registered on the NetProfiler server before you can begin profiling. Instruments can be registered using the form below and by following the same procedure described above to create your NetProfiler account.

The NetProfiler guided learning tutorial will walk you through the login process. If you have any questions, please email casupport@xrite.com or call us at 1-888 826-3042, option #2



NetProfiler Account Setup Form

Please complete the following list:

NetProfiler Account Setup Information		
Organization Name		
NetProfiler Administrator Name		
NetProfiler Administrator Title		
Phone #		
Fax #		
E-Mail Address		
Signature of Supervisor		
Date Approved		
Instrument Serial #'s		
Instrument Model #		
NetProfiler Tile Set(s) #'s		
X-Rite Sales Order #		

The NetProfiler Administrator has full access to all functions and information concerning your NetProfiler account(s) and will have the ability to:

- Create users and set up access levels for your account
- Create sub-organizations if your company has more than one location and/or department using
 NetProfiler

Please fax or email this form to:

Fax: 616-803-2076

Email: casupport@xrite.com

Once your account is set up, we will email your account information to your NetProfiler Administrator.

If you have any questions or need any further information, please do not hesitate to contact us at 1-888-826-3042, or via email at CASupport@xrite.com.