

CAUTION:

Do not attempt to connect the SE30-177 AC adapter that you received with your new 331C or 341C into an older style 331 or 341 instrument. Doing so **will** cause damage to the older 331 or 341 instrument. The polarity on the SE30-177 AC adapter input plug is the reverse of the old style adapter input plug.